



PL-01 General Photo Log 3.1

Project	Rachel Test 2
ID	413172
Survey Date	12/19/2023
User	Rachel Roden
Project Name	Pipeline Project
Project Location	Along the river
Monitor Name	J. Archaeologist
Describe Monitoring Activities	This is the description of all the monitoring activities observed today. This is the description of all the monitoring activities observed today. This is the description of all the monitoring activities observed today.

Photo(s)

#	Direction	Description of Photo Point	Location	Lat/Long of Photo	Township	Range	Section	Soil Color	Soil Texture
R1	North	Road to the pipeline	The Road	[35.06710576665007, -81.04151784718489]	12	18	20	10YR 3/3 / Dark Brown	Loam / Loam
R2	South	Fenceline	The Pipeline	[35.06711060812487, -81.04149999878008]	12	18	21	10YR 4/3 / Brown	Loamy Sand / Loamy Sand
R3	NorthEast	Vegetation	Near the Pipeline	[35.06707730948855, -81.04150942832632]	13	18	10	10YR 3/4 / Dark Yellowish Brown	Loam / Loam
R4	SouthEast	Access Road	South Access Road	[35.06710273004355, -81.0414859675721]	13	18	11	10YR 3/3 / Dark Brown	Clay Loam / Clay Loam

Photo

R1 - P1



Photo Point 1

R2 - P1



Photo Point 2



R3 - P1



Photo Point 3

R4 - P1



Photo Point 4